

MOBRIDGE
221 NO MAIN
DAVES COIN
02742
SD 57601



Lieberman Music Company
9549 Penn Avenue South · Minneapolis, Minnesota 55431

LMC

SPECIALS OF THE MONTH

WHILE THEY LAST!

ATARI ASTEROID
SWITCH & HOLDER
REG. \$3.25

\$2

ASSORTED T-SHIRTS
Reg. \$6.95


\$5.75

NEW NOVUS PLASTIC POLISH &
SCRATCH REMOVER
REG. \$3.95 each

\$3.35

4-WAY UNIVERSAL JOYSTICKS
LOTS OF
10 OR MORE

\$19 \$17.50



Greg Rutherford
LMC parts manager

Lieberman Music Company

LOCAL - 887-5300

MN. WATS 800-352-2802

OUT-STATE 800-328-2960

LMC News Notes

volume 2, Number 2

July 1982

Service Bulletins From MIDWAY MFG. CO.

GAMES: MS. PAC-MAN & GALAGA
SUBJECT: WAVY OR DISTORTED VIDEO WITH STATIC FILTER BOARD

MODIFICATION:


1. Remove yellow ground strap from transformer leg and secure it to the line filter assembly mounting screw (metal case is earth ground).
2. Check for loose ground straps.

GAMES: RALLY X, GALAGA & BOSCONIAN
SUBJECT: POWER SUPPLY (A084-90414-C935)


1. Power supply A084-90414-C935 has been revised and the new Part Number is A082-90420-B000.
2. The A084-90414-C935 and the A082-90420-B000 power supplies are interchangeable.
3. I repeat, either power supply will function in Rally X, Galaga & Bosconian.

centuri

Engineering Change Notice



GAME: PAC-MAN & MS. PACMAN
SUBJECT: INTERMITTENT LOSS OF SOUND (STATIC)
MODIFICATION:
1. Cut trace to pin #1 of 2M (74LS273).
2. Solder 1K resistor from +5VDC to pin #1 of IC 2M. (See Figure #1)



GAMES: MS. PAC-MAN, KICKMAN & GALAGA
SUBJECT: WELLS-GARDNER COLOR MONITOR (19K4900 & 13K4800)
CONDITION: Loss of vertical deflection (white line down center of screen).
REMEDY: Check C313 (47/160V) capacitor for loose solder connection.



Cecil Waulk, LMC operations manager

Service Note All Seeburg Phonographs

Symptom: Erratic trip, multiple plays, trip lever binding.

Solution: Inspect top of trip solenoid bracket for signs of copper plug being above the flat surface or missing. This can cause the plunger to stick in the plug. Replace, if necessary. (Plug number 245576).
Jerry Johnston, L M C

Post Your Notes!

We've noticed that notes on repair jobs and P.C. Boards have diminished drastically over the past year. Your notes are a great help to our technicians in determining the problem and the time it will take to repair the merchandise. Include the following information in your notes:

1. It it under warranty?
2. Date of purchase
3. Serial Number
4. Type of game
5. The problem
6. Running time before problem occurs.
7. What work has already been done on the item.

Thanks for your help. It will speed things up.

John Boisvert, L M C

Engineering Change Notice System: THE PIT

ECN No. 380-03
Date Issued: 4/14/82
Part No. 377-12-0100
C.P.U. Harness

Change Requested: Change speaker wire in location "Y" to location "4" on edge connector. This change is done to eliminate the heat problem on the speaker.

DWG/BILL of MTL Changes:
C.P.U. Harness Drawing has to be changed accordingly (see diagram at left).