



## Data East Service Advisory

To: Service Manager  
From: Data East Service Department  
Date: July 6, 1992  
Subject: Possible High Voltage Failures on the Power  
Supply P.C.B.

Recently, we have seen sporadic failures in the High Voltage section of the Power Supply board. We believe these failures to be caused by a bad batch of Zener Diodes or an excessive in-rush current, primarily during the power-up phase of the game.

As a precautionary measure we have changed vendors of our Zener diodes and have added a 1.5K ohm 1/2 Watt resistor in series with the base of TR6 on the Power Supply board to minimize the in-rush current. (See attached schematic)

Because this condition may occur on the early production of Lethal Weapon 3, we are sending each distributor with suspect games, an allotment of power supply boards with the modification installed. As you replace each board please send the defective boards back to Data East Pinball.

If you have any questions please contact Jim or Arnie in the Data East Service Department.